DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-003552

Address: 333 Burma Road **Date Inspected:** 18-Aug-2008

City: Oakland, CA 94607

Project Name: SAS Superstructure **OSM Arrival Time:** 1400 **OSM Departure Time:** 2300 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Chen Chih Ming No Yes N/A **Rod Oven in Use:** Yes **Inspected CWI report:** No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component:** OBG side, bottom and deck panels

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance Inspector (QA) Steve Hall was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA observed and/or found the following:

OBG new assembly bay 2

QA observed ZPMC personnel flame straightening one diaphragm plate at PP-026 in corner assembly identified as CA 12.

QA observed ZPMC qualified welding personnel SMAW 4G R1 UT repair on SEG-019A-023 following the guide lines of WPS-345-SMAW-4G (4F)-repair. Two areas on this weld were rejected by ZPMC QC UT technician identified as Xu Rong gang on 7/26/08. QC monitored the weld repair process continuously until complete. The welder ID and welding parameters as measured with Quality Controls calibrated instruments appeared to be in conformance with the posted WPS's and were as follows:

Volts: 24.5 Amps: 172 Travel speed: 108mm/min

Welder ID: 066258

Other general observations include ZPMC personnel fitting and welding OBG temporary support columns, grinding and weld bevel prep on various OBG components.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)



Summary of Conversations:

Only general conversations were held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Ryan Smith, (858) 232-6799, who represents the Office of Structural Materials for your project.

Inspected By:	Hall,Steven	Quality Assurance Inspector
Reviewed By:	Cuellar,Robert	QA Reviewer